UNIVERSITY OF CALICUT

UNIVERSITY SCIENCE INSTRUMENTATION CENTRE

QUOTATION NOTICE

Date: 19.04.2018

No: 115362/USIC-Asst-1/2016/Admn

Reg No of the vehicle	KL 65-9
Vehicle Make	Tata Sumo
Repair Work	1. Steering tight
	2. Clutch tight
	3. Main glass (patch work)
	4. Mud guard patch work
	5. Leaf set bush sound
	6. Electrical check up
	7. Body touch up and polish
	8. Engine oil
	9. Gear lever play
Last date and time of	
the receipt of the	30.04.2018
quotation	
Date and time of	02.05.2018.
opening the quotation	UZ.U3.ZU 18.
Designation and	
address of the office to	The Instrumentation Engineer, USIC, University of
whom the quotation	Calicut, Malappuram(dist)- 673635.
are to be sent	

- 1. Sealed comprehensive quotations are invited for the emergency repair work for the vehicle KL 65-9 (Tata Sumo).
- 2. The quotation should reach the Instrumentation Engineer, University of Calicut on or before 05.05.2018. The quotations received late, will be rejected summarily.
- 3. The rate quoted should be inclusive of all charges including taxes,levies,transportation charges.
 - 4. The repair work should be completed at the earliest, after receiving the work order.

Terms and Conditions:-

- 1. The bidder should have valid GST registration.
- 2. The bidder should clearly mention the rate for the spare and the labour.

INSTRUMENTATION ENGINEER

То

The System Analyst, Digital Wing(for publishing in the University web site).