

**QUOTATION NOTICE**

<b>Reg No of the vehicle</b>	KL 55 C 624
<b>Vehicle Make</b>	Mahindra Bolero
<b>Work Type</b>	<p align="center"><b><u>Repair Work (including spares)</u></b></p> <ol style="list-style-type: none"> <li>1. Removing and refitting gear box assy.</li> <li>2. Removing clutch Assy setting and refitting.</li> <li>3. Gear box Assy dismantling, cleaning wornout spares changing and setting charges.</li> <li>4. 4 wheel brake cleaning and setting.</li> <li>5. Removing brake pads, scraping and refitting.</li> <li>6. Replacing rear brake shoe Assy and setting.</li> <li>7. 4 wheel Hub greese oil seals and bearing grease changing.</li> <li>8. Replacing speedo metre cable assy and correcting.</li> <li>9. Replacing water pump Assy.</li> <li>10. Removing and refitting Propeller shaft Assy.</li> <li>11. Centre Joint cross and cup shimming.</li> </ol>
<b>Last date and time of receipt of the quotation</b>	On or before 31.01.2018
<b>Date and time of opening the quotation</b>	01.02.2018.
<b>Designation and address of the office to whom the quotation are to be sent</b>	<p align="center">The Instrumentation Engineer, USIC, University of Calicut, Malappuram.</p>

1. Sealed comprehensive quotations are invited for the emergency repair work for the vehicle KL 55 C 624 (Mahindra Bolero).
2. The quotation should reach the Instrumentation Engineer on or before 31.01.2018. The quotations received late, will be rejected summarily.
3. The rate quoted should be inclusive of all charges including taxes, levies, transportation charges.

However the base rate, GST and other charges if any should be shown separately.

4. The repair work may be done at the earliest after receiving the work order.

**Terms and Conditions**

1. The bidder should have GST registration.

2. The bidder should clearly mention the Total cost, the cost for the spare parts and the labour cost separately.

**Instrumentation Engineer**

**To**

The System Analyst, Digital Wing (For publishing in the University Website)